


All photos by Brian Estes



Top left: several lesson plans and notes were still found written on the boards in a few classrooms, including the message pictured above.

Top right: the back wall of the theatre is still painted from the production of *Guys and Dolls* last spring.

Above: severe damage was incurred to the classroom on the second floor across from the social science division suite

Right: the lobby on the first floor that leads into the Weymss Auditorium. Little visible damage was incurred to first floor hallways, but the main entry hallway is now being used for storage.

Bottom left: the roof of Weymss was torn off, forcing maintenance crews to construct a protective wood covering over the affected areas.

Bottom right: the classroom on the second floor next door to the one pictured above.

